


# Transformer Chemistry Services[TCS]

**THE LEADER IN CONDITION ASSESSMENT**

*Specialists in Testing, Diagnostic for the Electrical Power Industry*



**PREDICTIVE MAINTENANCE THROUGH TRANSFORMER OIL ANALYSIS**

***INCREASING YOUR PROFITS AND PRODUCTIVITY***

# Overview

TCS. is an independent laboratory and consulting firm that specializes in diagnostic testing of insulating materials used in high-voltage electrical equipment.

*Established in 1992 as the first commercial laboratory to offer gas-in-oil and Furanic analysis in South Africa.*




# Chemical Reactor



That just happens to Transform Electricity




# TRANSFORMERS DO FAIL



In the event of failure , the force applied to the structure may approximate 360 PSI due to the steep wave front and high velocity , representing a loading sufficient to distort the container or shear the holding bolts and possibly cause a transformer oil fire.

# TRANSFORMER FAILURE MODE



*Figure 1.76 - Transformer failure rate "Bathtub Curve": (A) is failures due to infant mortality; (B) is constant failure rate (random); and (C) is failures due to aging. (R. Sahu, "Using Transformer Failure Data to Set Spare Equipment Inventories"-1980).*

## **Importance of Transformer Maintenance**

# Modern Transformers

The increased stress require more frequent and improved Condition Monitoring

*The fault free operation of power transformers is of major economic/safety importance to power utilities and industrial consumers of electricity.*



**1,500 KVA  
1945**



**1,500 KVA  
1970**


# The application of Dissolved Gas

## Analysis(DGA)

The insulating oil is capable of dissolving gases in the event of developing faults in the transformer

These gases are extracted from the oil →

Analysed by the sophisticated technique of Gas Chromatography.



**Diagnosis methods are utilised to diagnose the type and severity of the fault occurring in the transformer.**

# Dissolved Gas (DGA)

Universal accepted method of choice to locate incipient thermal and electrical faults

DGA methodology and applicability have evolved significantly since its inception 30 years ago.

There are various interpretation Codes for diagnosis

*The interpretation should be left to a specialist and his advice and recommendations should be followed.*

**The incorrect diagnosis can lead to costly  
Transformer failure**



# Sapref Petroleum Refinery

Voltage: 6.6 kV



Rating: 1250 KVA

Diagnosis: Partial Discharge(Corona)

Condition Code 4

Findings The core of the transformer was found to be delaminating due to corrosion caused by high humidity( 73 ppm water in oil)

Savings: R Hundred Thousand range possible **R Million range** if the Transformer failed with Fire



## CORONA in Transformer Oil


CORONA IN TRANSFORMER OIL	
HYDROGEN (KEY GAS)	— 86.0% of Combustibles
Methane	— 13.0% of Combustibles
Carbon Monoxide	— 0.2% of Combustibles
Ethane	— 0.5% of Combustibles
Ethylene	— 0.2% of Combustibles
Acetylene	— 0.1% of Combustibles



# Tongatt-Hulett's Refinery

6.6 kV 1000 KVA

Conduction and Ionisation (Partial discharge)  
Cellulosic Degradation-impending insulation failure





## OVERHEATED

### Cellulose

#### OVERHEATED CELLULOSE

CARBON MONOXIDE (KEY GAS)	—	92.0% of Combustibles
Hydrogen	—	6.7% of Combustibles
Methane	—	1.2% of Combustibles
Ethane	—	0.01% of Combustibles
Ethylene	—	0.01% of Combustibles
Acetylene	—	0.01% of Combustibles








# UMGENI WATER

Voltage: 11/6.6 kV

Rating 5000 KVA



OVERHEATING OF TRANSFORMER OIL		
ETHYLENE (KEY GAS)	—	63.0% of Combustibles
Ethane	—	17.0% of Combustibles
Methane	—	16.0% of Combustibles
Acetylene	—	Trace
Misc. Gases	—	Trace



**OVERHEATING  
of Transformer Oil**

*Analysis/Diagnosis:*

**Condition Code 4**

The DGA indicated a Thermal Fault 300-700 Deg C

*Findings:* Various Copper to Aluminium (bi-metal) connection's were found burned

**Savings:**

The transformer was repaired at the Manufacturer cost, i.e First year warranty




ARCING IN TRANSFORMER OIL	
Hydrogen	— 60.0% of Combustibles
ACETYLENE (KEY GAS)	— 30.0% of Combustibles
Methane	— 5.0% of Combustibles
Ethane	— 1.6% of Combustibles
Ethylene	— 3.3% of Combustibles

# NORDBERG SMELTER

## FURNACE 10 TON

Voltage: 11 kV/5250v

Rating: 3000 KVA



The DGA analysis indicated a Discharge of High Energy(Arcing)

**Condition Code 4**


*Note: The Electrical tests- Meghom Meter(Insulation Resistance) passed*

*Caution: In the event of a unit trip conduct a DGA before Re-energising*




## ESKOM: Chivelston Substation

Voltage: 400/275 kV Rating: 400MVA



*Diagnosis:* The Dissolved Gas Analysis indicated a Thermal Fault Of High Temperature >700 DegC  
*Note: Calculated time to Buchholz activation: 2 years*

*Findings:* The core of this shell form transformer was found to delaminating



*Savings:* **R Million Range**

The Distribution losses had the transformer failed would have been catastrophic (50% of KZN affected)




# HILLSIDE ALUMINIUM

## Interconnector

Voltage: 132 kV Rating:90.8/93.5MVA



***Analysis/Diagnosis:*** The Interconnected system Tripped on Buchholz 6 months after energising. The manufacturer suspected a Corona Fault on the cable housing. The DGA analysis indicated a Thermal Fault(300-700 degC) in the Bottom Chamber. **CONDITION Code 4**



***Findings:*** Burnt connections in the Bottom Chamber due to non-conforming quality control during installation



***Savings:*** By accurately diagnosing the fault type and location the manufacturer saved significant time and equipment to effect repairs. The smelter saved minimum down time on production


**The savings achieved were in  
R Millions Range**

# ESTCOURT TLC

Voltage: 33/11/6.6 kV Rating: 15 MVA

## Analysis/Diagnosis

The DGA analysis at 21/07/1997 indicated a Thermal Fault  
The maintenance contractor recommended Power-on oil purification. i.e *highly dangerous and irresponsible as further damage is likely, with additional costs to the transformer owner*



The DGA analysis 30/04/1997 indicated a Discharge of High Energy(Arcing)  
The transformer was having Power-On oil purification at the time of the Buchholz Alarm

© Copyright 2001

# ESTCOURT TLC

Voltage: 33/11/6.6 kV      Rating: 15 MVA

## *Analysis/Diagnosis*

Discharge of High Energy due to failed Off-load Tap changer

## *Findings*



All phases had burning

The inner contact ring of the center phase had failed.

*Note: The center phase of the tap changer was directly below the pipe from the conservator tank. i.e. Flow of oil was over this point*

**Savings: In excess >R 300 000**

The transformer was repaired on site and returned to service




# Case Study 3 Faults: Mondri Merebank

Voltage: 33kV Rating: 30 MVA

Client Name: MONDI MEREBANK  
Substation: 33kV

SerialNumber: J5443/1  
Transformer: 10 HT 6

## Dissolved Gas Graph



Unit Trip 11/01/1999  
DGA: Thermal Fault High  
Temperature  
Sent to works facility for repairs


DGA: 27/11/2000 Indicates  
Thermal Fault  
CONDITION CODE 4  
See DGA graph range



Client Name: MONDI MEREBANK  
Substation: 33kV  
SerialNumber: 35443/1  
Transformer: 10 HT 6

Close Graph

### Dissolved Gas Graph



Purification  
To Degas

Burnt CT

Burning HT

Burnt Internal  
Connection







**BURNT CURRENT  
Transformer**





## Analysis/ Diagnosis:

The oil was sampled to monitor the internal condition following energizing after repairs of a previous fault.

The DGA analysis indicated a Thermal Fault in the main tank.

## Findings:

The center and outside connections were burnt due to bad contact between the copper bar and the bushing stud. Closer inspection shows that stud/hole diameter of the copper bar was oversized so that only the points of the connection nut were making contact. This reduced the area of contact required for normal current flow conditions.



## Transformer sent to Works Facility



Burnt connection found  
Within the windings.  
Note: Windings removed at  
Repair facility





# Hillside Aluminum

22 kV Reactor 1075 KVAR

## ANALYSIS/DIAGNOSIS

*THERMAL FAULT OF OF HIGH  
TEMPERATURE RANGE > 700 Deg C*

IEC 599: GAS PRODUCTION RATES

**CONDITION 4** -Ethylene(C<sub>2</sub>H<sub>4</sub>)-Significant

**FINDINGS: Burning on the Resistor**

*CAUSES: Fourth Harmonic being amplified causing the transformer to be subjected to 10 times its rated current(milli seconds) i.e Design Fault System*

**SAVINGS IN THE MILLION  
RANGE**

or in the Billion Range due the  
knock on effect

Burning occurring on resistor bank

